

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 189 Const Calendar Day: 413 Date: 26-Oct-2010 Tuesday

Inspector Name: Daouk, Sami Title:

Inspection Type: Continuous

Shift Hours: 07:00 pm 05:30 am **Break**: 00:30 **Over Time**: 02:00

Federal ID: Location:

Reviewer: Soheilifard, Saman Approved Date: 05-Nov-10 Status: Approved

Weather

Temperature 7 AM 12 PM 4PM

Precipitation Condition Sunny

Working Day | If no, explain:

Diary:

Tower Activities

ABF night crews came to the site at 6:00 PM. Crews had to work on the West tower shaft lift 2 erection . They started after the morning crews left at 6:30 PM.

Tony , Samuel , & Ryan had to work on the gantry . Carlos , Augie , Jacob , & Kevin had to work on the erection & bolts installation .

The West tower shaft was above the East cross member on the erection tower at 7:00 PM. Tony started to mobilize the shaft to the North West corner at 7:05 PM. The West tower shaft was above lift 1 shaft at 8:00 AM. Crews had to rotate lift 2 shaft , adjust the splice plates on lift 1 & lower the shaft . Lift 2 West shaft was on the top of the lift 1 (Touch Down) at 8:15 PM. Samuel & Ryan joined the other crews to help at 8:00 PM.

Crews had to use hydraulic jacks on sides A & E to bring the splice plates against the shaft skins, drive drift pins, instal, & snug 28 bolts on each splice plates. (Total 140 bolts). Crews were done at 8:45 PM.

After that , Carlos , Ryan , & Samuel had to release the gantry , & pull the holding plates . Crews started at 8:50 PM. They were done at 11:30 PM.

Augie , Jacob , & Kevin had to pretension the bolts , run lights , & prepare the East tower shaft lift 1 for lift 2 erection . Crews had to drive drift pins , mount 4 jacks on A & E splice plates , prepare the bolts , washer , & nuts . Crews were done at 11:30 PM.

Then , all crews had to work with Enerpac technicians on the North strand jack . The gantry North strand jack had oil leak . crews had to cut the strands disassemble the jack , fly & set it on the E line . Crews were done at 12:30 AM.

Enerpac technicians had to remove the top portion of the jack , check & try to change the broken seal , but they did not have the seal on the site . They were done at 3:00 AM.

Tony started to mobilize the gantry East at 12:30 AM. (10/27/2010) . He started to lower the swindle using one strand jack at 1:00 AM. At 5:00 AM. The swindle was at 50 meters elevation . Night crews left at 6:30 AM.

04-0120F4 Bid Item: T-L01-JSS.053 Tower Lift 01 Jacking System and Shims AMERICAN BRIDGE/FLUOR, A JV 04-0120F4 Bid Item: 053 T-L02-STE.053 Tower Lift 02 Strut East Erect structural steel (bridge tower) AMERICAN BRIDGE/FLUOR, A JV Labor Class RT Hrs OT Hrs DT Hrs Total Remarks Dispute Trade Name

Page 1 of 2

Run date 21-Nov-14

2:52 PM

Time

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name Daouk, Sami Diary #: 189 Date: 26-Oct-2010 Tuesday Contractor: AMERICAN BRIDGE/FLUOR, A JV JNM 2.00 Ironworker SAMUEL TORRECILLAS 8.00 1.50 11.50 APP 2.00 8.00 1.50 11.50 Ironworker RYAN EVANCHIK Operator OTH NICOLAUS SHAFER 0.00 2.00 1.50 3.50 Ironworker JNM **KEVIN RATCLIFF** 8.00 2.00 1.50 11.50 Ironworker APP JACOB MECHE 8.00 2.00 1.50 11.50 Ironworker FOR CARLOS VALVERDE 8.00 2.00 1.50 11.50 APP Ironworker **AUGIE SOLIS** 8.00 2.00 1.50 11.50 Ironworker JNM ANTHONY COSTA 8.00 2.00 1.50 11.50 Equipment Rental Company **Equipment ID** Description RT Hrs OT Hrs ST Hrs IT Hrs Remarks Dispute Contractor: AMERICAN BRIDGE/FLUOR, A JV 743 Marine, Barge, Flexifloat 1 EM1010 No 0.00 0.00 0.00 0.00 *E0090562 TOWER CRANE No 8.00 4.00 0.00 0.00

